

1/5

Fig. 1







Fig. 2



BEST AVAILABLE COPY

2/5

Fig. 3




3/5

Fig. 4


initial defective region  
(right side of dotted line)      regeneration of cartilage tissue  
in defective region scaffold implanted

normal region



regenerated cartilage tissue

enlarged image



three dimensional scaffold  
(most are degraded and portions remain)

BEST AVAILABLE COPY

Fig. 5




Fig. 6




Fig. 7

